

| CLASS | RATING | LIMITATIONS |
|------------|----------------------------|---|
| Engines | B1 Engines | P&WC PT6 Series HSI Repairs, PT First Stage Stator Repl. Access. Gearbox Field Rep. P&WC PT6 Series Borescope inspection incl removal/installation of fuel nozzles |
| Components | C5 Electrical power | 24-30 Batteries |
| | | NICKEL-CADMIUM BATTERIES |
| | | SAFT 023510-000 |
| | | SAFT 024054-000 (257CH-9) |
| | | SAFT 024055-000 (427CK-1) |
| | | SAFT 024147-000 (539CH-1), also includes ELDEC P/N BA35-01 and BOEING P/N S282T003-1 |
| | | SAFT 151CH1 |
| | | SAFT 151CH2 |
| | | SAFT 1606 Series |
| | | SAFT 1656 Series |
| | | SAFT 1658 Series |
| | | SAFT 1756 Series |
| | | SAFT 178CH1 |
| | | SAFT 23175 |
| | | SAFT 23176 |
| | | SAFT 2376 Series |
| | | SAFT 2378 Series |
| | | SAFT 27478 |
| | | SAFT 2758 |
| | | SAFT 4000A1 Series |
| | | SAFT 40178 Series |
| | | SAFT 40208 Series |
| | | SAFT 40253 |
| | | SAFT 40308 Series |
| | | SAFT 40576 Series |
| | | SAFT 40678 Series |
| | | SAFT 4076 Series |
| | | SAFT 4078 Series |
| | | SAFT 409CH2 |
| | | SAFT 4417CH14 |
| | | SAFT 441CH1 |

| | | |
|------------|----------------------------|-------------------------------|
| Components | C5 Electrical power | SAFT 447CH7 |
| | | SAFT 447CH8 |
| | | VARTA / HAWKER F20/40H1CT |
| | | VARTA / HAWKER F20/40H1CT3 |
| | | MARATHON ATSP-44 (30978-002) |
| | | MARATHON BTCA5-20 |
| | | MARATHON BTSP-400 |
| | | MARATHON BTSP-900 |
| | | MARATHON CA-101N |
| | | MARATHON PTSP-440 (31406-003) |
| | | MARATHON SP-170A |
| | | MARATHON SP-376 (30596-001) |
| | | MARATHON 23661-001 |
| | | AERO DESIGN AD-4078 Series |
| | | LEAD ACID BATTERIES |
| | | CONCORDE RG-126 |
| | | CONCORDE RG-206 |
| | | CONCORDE RG-224 |
| | | CONCORDE RG-24 Series |
| | | CONCORDE RG-25 Series |
| | | CONCORDE RG-355 |
| | | CONCORDE RG-380E Series |
| | | CONCORDE RG-390E/H Series |
| | | CONCORDE RG-41 Series |
| | | CONCORDE S3597 Series |
| | | GILL G-242 |
| | | GILL G-243 |
| | | GILL G-246 |
| | | GILL G-247 |
| | | GILL G-6381E |
| | | GILL G-639E |
| | | GILL G-641 |
| | | GILL 7638-44T |

| | | |
|------------|----------------------------|--|
| Components | C5 Electrical power | HAWKER 7624308001 |
| | | HAWKER 7624308001-003 |
| | | HAWKER 90-00134-001 |
| | | HAWKER 9750W0538 |
| | | HAWKER 9750W0640 |
| | | HAWKER 9750W0840 |
| | | HAWKER 9705W0370-11 |
| | | HAWKER 9750E0640 |
| | | HAWKER F0773-3005 |
| | | L-3 PS-835 |
| | | L-3 PS-850 |
| | | SECURAPLANE 9750W0390-5 |
| | | SECURAPLANE 100-2410-04 |
| | | TRUE BLUE POWER (MID CONTINENT) MD421 Series |
| Components | C6 Equipment | 25-10, 25-20, 25-30, 25-40 For aircraft in the scope of work 25-20 Inspection/Repair/Modification of Upper Support Assy P/N BAM00830 (Part revision A & B) 25-60 Programming and Maintenance Level 2 on Compact and Integra ELT Models 25 Inspection and repair of Avcon Retractable EO/IR Assembly P/N 1817602-101 25 Repair by replacement of parts on AeroLite Plattform P/N 024-0295050-501/-503 |
| Components | C7 Engine-APU | 71 Cowlings: Removal of Paint, Inspection, Repair and Paint 71 Engine Truss Assembly: Removal of Paint, Inspection, Repair and Painting acc. Approved Data 71 Fire Seals: Repair by Riveting of Doublers acc. Approved Data 71 Engine Vibration Isolation System: Disassembly / Assembly, Testing, Cleaning, Check, Repair of Barry Controls Aerospace Type 5906/95007 and 93880/95596 73 P&WC PT6 Series Fuel Nozzles: Removal / Installation, Cleaning, Inspection, Adjustment, Test 78 Exhausts: Repair by Welding acc. Approved Data 79 Oil Coolers and Reservoirs: Repair by Welding acc. Approved Data |
| Components | C9 Fuel | 28 SMC Auxiliary Fuel Tank; Overhaul of BAM EASA.21J.339 P/N BAM00601C |
| Components | C8 Flight Controls | 27, 55, 57-40, 57-50, 57-60, 57-70 Repairs and alterations of complete aircraft within the scope of work (MOE 1.9) including structural components and parts of such aircraft. 27, 55, 57-40, 57-50, 57-60, 57-70 Repair and alteration of aircraft structural components/parts, not included in the Company scope of work. |

| | | |
|----------------------|-----------------------------------|--|
| Components | C14 Landing Gear | <p>32-40 Inspection/overhaul and replacement of tires and parts belonging to all aircraft/helicopters i.a.w current technical data held by the company.</p> <p>32-40 Beech P/N 101-8002-3 Limitation, Installation of ice shield</p> <p>32-10, 32-20 Beech 90/F90/100/200/300/1900 Inspection and Overhaul</p> <p>32-50 Beech 90/F90/100/200/300/1900 Shimmy Damper Inspection and Overhaul</p> <p>32-70 Floats; Repair iaw Approved Data</p> <p>32 Airbus EC145 Ice Grip Plate: Repair of BAM EASA.21J.339 EPA P/N BAM01011A, BAM01013A, BAM01015A</p> <p>32 LDG: Repair by welding IAW Approved Data</p> |
| Components | C20 Structure | <p>53, 54, 57-10, 57-20, 57-30 Repairs and alterations of complete aircraft within the scope of work (MOE 1.9) including structural components and parts of such aircraft.</p> <p>53, 54, 57-10, 57-20, 57-30 Repair and alteration of aircraft structural components/parts, not included in the Company scope of work.</p> <p>57-20 Installation/Replacement/Repair of BLR Beechcraft King Air Winglet System</p> |
| Specialised Services | D1 Non Destructive Testing | <p>Magnetic Particle MT Level II: "Hand Yoke" on all aircraft components for which current maintenance data is held by the company.</p> <p>Liquid Penetrant Level II: On all aircraft components for which maintenance data is held by the company.</p> <p>Eddy Current Level II: On all aircraft components for which maintenance data is held by the company.</p> |